

TRANSFER REMOVAL SPRAY

XP2029

Xpres' Transfer Removal Spray is the perfect solution to remove misplaced heat transfers.

STEP BY STEP

STEP 1

Shake the can well before use.

STEP 2

Spray onto the transfer from the underside (inside of the garment).

STEP 3

Leave for approx 1 minute to allow application to react with the transfer.

STEP 4

Peel away the transfer from the garment.

COMPATIBILITY CHART

XP3016 - SUPERFLEX

XP3018 - EASY FLEX

XP3057 - PEARL

XP3041 - METALLIC

XP3160 - ECO FLEX

CARE INFORMATION

Extremely flammable. Store at a moderate temperature in a dry, well ventilated area. Keep away from heat, sparks and open flame.

Pressurized container: protect from sunlight and do not expose to temperatures exceeding 50 degrees.

PLEASE SEE SAFETY DATA SHEET FOR ANY FURTHER INFORMATION.

PLEASE NOTE: The sellers and manufacturers maximum obligation shall be to replace any product that has been proven to be defective. Neither the seller nor the manufacturer of Transfer Removal Spray be liable for any injury direct or consequential, arising out of the use of, or inability to use this product.



Web: www.xpres.co.uk Support www.xprestechnical.co.uk

Oakridge Park, Trent Lane, Castle Donington, Derby DE74 2PY Phone: 01332 855 085 E-mail: sales@xpres.co.uk